


Pleated and Duopleat blinds



How to measure windows correctly?

Step 1.



During measurement of the width and the height we take into account the diameter of the pane(dimension of pane). It is the best to measure the width from one black gasket including it to another black gasket without its dimension.

Step 2.



We have to pay attention also to dimension of the width of glazing bead. It must have at least 1 cm(the width marked in figure) for standard clamping.